



ecology and environment, inc.

101 YESLER WAY, SEATTLE, WASHINGTON, 98104, TEL. 206/624-9537

International Specialists in the Environment

MEMORANDUM

DATE: November 23, 1988

TO: John Osborn, FIT-RPO, USEPA, Region X

THRU: Jeffrey Villnow, FIT-OM, E & E, Seattle JV

FROM: J.B. Hunt, FIT-SM, E & E, Seattle JH

SUBJ: Site Inspection Recommendations
Draper Tractor Parts, Inc.
Spokane, Washington

REF: TDD F10-8808-15
PAN FWA0192SA

CC: Deborah Flood, HWD-SM, USEPA, Region X
Lynn Guilford, FIT-PM, E & E, Seattle

The Draper Tractor Parts, Inc. site has been investigated by Golder Associates from 1985 to July 1987 as part of an ongoing remedial investigation/feasibility study (RI/FS). The RI/FS was conducted at the request of the Washington Department of Ecology-Eastern Regional Office (Ecology) as a result of prior preliminary assessment activity at Draper Tractor and Tosco Corporation. While no work has been conducted on this site since July 1987, Ecology is currently considering enforcement proceedings against the involved potentially responsible parties (PRPs) for generation of funds for further work (completion of Phase III, RI/FS). Promulgation of the enforcement directive will proceed under the Washington State Superfund Program.

As all of the contaminants found during the Draper Tractor SSI are petroleum constituents, additional on-site sampling will be required to determine the existence of non-petroleum exclusion wastes. EPA should periodically monitor further investigative progress at the site to ensure that EPA concerns are adequately addressed.

JH:csr

Enclosures

USEPA SF



1556160